

Issues

#	Project	Tracker	Status	Priority	Subject	Author	Assignee	Updated
3597	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	disk 5-000cca-2a3ce3557 in work15f failing (/dev/sdak)	Carsten Aulbert	Henning Fehrmann	2025-04-15 08:30
3567	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in work15c	Carsten Aulbert	Henning Fehrmann	2025-02-18 12:38
3566	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in einstein-home	Carsten Aulbert	Henning Fehrmann	2025-02-18 08:37
3542	Atlas	ToDo	Assigned	Normal	Empty out rack 101	Carsten Aulbert	Henning Fehrmann	2024-12-12 14:13
3535	Atlas	ToDo	Assigned	Normal	LCP cmc 38 is broken	Carsten Aulbert	Henning Fehrmann	2024-11-06 12:05
3517	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Failed disk in workbackup04	Carsten Aulbert	Henning Fehrmann	2024-10-24 06:57
3504	Atlas	ToDo	Assigned	Normal	Clean disks/BMC passwords of all Asus nodes to be removed from cluster	Carsten Aulbert	Henning Fehrmann	2024-08-06 10:37
3499	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in work15j	Carsten Aulbert	Henning Fehrmann	2024-08-05 09:57
3482	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken Disk in work59i	Carsten Aulbert	Henning Fehrmann	2024-06-10 07:24
3470	Atlas	Hardware Repair	Assigned	Normal	HDD exchange in workbackup02 and workbackup05	Henning Fehrmann	Henning Fehrmann	2024-06-10 08:01
3382	Atlas	Hardware Repair	Assigned	Normal	defective power supply unit from the door control in rack 59 and 60	Lukas Hagemann	Henning Fehrmann	2023-08-17 15:24
3304	Atlas	Bug	Assigned	Normal	prometheus SMART monitoring	Sven Renas	Henning Fehrmann	2023-03-30 14:50
3280	Atlas	Bug	Assigned	Normal	prometheus exporter failing sometimes	Sven Renas	Henning Fehrmann	2023-02-13 14:46
3272	Atlas	Support	Assigned	Normal	unwanted behaviour of racktemp.rb	Sven Renas	Henning Fehrmann	2023-02-06 14:09
3270	Atlas	Bug	Assigned	Normal	Monitoring of PSU failures for the datacore switch	Sven Renas	Henning Fehrmann	2023-02-06 14:47
3194	Warranty / Broken parts	Vendor/Govirtual(Huawei)	Assigned	Normal	Broken Disk in condor5	Carsten Aulbert	Henning Fehrmann	2023-01-13 15:43
3179	Atlas	Support	Assigned	Normal	raise cold water temeprature	Carsten Aulbert	Henning Fehrmann	2022-10-07 12:18
3163	Atlas	Hardware Repair	Assigned	Normal	Fancontroller2 of LCP09 has issues with powering its fans	Sven Renas	Henning Fehrmann	2023-06-19 13:15
3142	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in work60h	Carsten Aulbert	Henning Fehrmann	2022-12-12 10:45
3137	Atlas	Feature	Assigned	Low	make prom_checksmart.rb actually work with NVMe drives	Henning Fehrmann	Henning Fehrmann	2022-12-05 15:56
3124	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in worbbackup06	Henning Fehrmann	Henning Fehrmann	2022-04-12 08:41

#	Project	Tracker	Status	Priority	Subject	Author	Assignee	Updated
3113	Atlas	Feature	Assigned	Normal	Consider upgrading datacore to release 2712 or later	Carsten Aulbert	Henning Fehrmann	2021-11-04 08:52
3093	Atlas	Bug	Assigned	Normal	prometheus GPU errors	Carsten Aulbert	Henning Fehrmann	2021-09-08 10:16
3051	Atlas	ToDo	Assigned	Normal	Upgrade ZFS on promtheusserver to 2.0.x	Carsten Aulbert	Henning Fehrmann	2021-05-18 14:30
3033	Warranty / Broken parts	Vendor/Controlware(Huawei)	Assigned	Normal	Broken disk in work15c	Carsten Aulbert	Henning Fehrmann	2022-04-12 08:41
3015	Atlas	Bug	New	Normal	Create buster VM for Olli	Alexander Post	Henning Fehrmann	2020-10-21 12:01
2978	Atlas	Hardware Repair	Assigned	Normal	a5310 ipmitool sdr peculiarity	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:49
2977	Atlas	Hardware Repair	Assigned	Normal	a6501 ipmitool sdr peculiarity	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:49
2971	Atlas	Hardware Repair	Assigned	Normal	a4406 ipmitool sdr peculiarity	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:49
2970	Atlas	ToDo	Assigned	Normal	a8206 old HDD FW	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:42
2969	Atlas	ToDo	Assigned	Normal	a8205 old HDD FW	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:43
2968	Atlas	ToDo	Assigned	Normal	a7410 old HDD FW	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:43
2967	Atlas	ToDo	Assigned	Normal	a7309 old HDD FW	Henning Fehrmann	Henning Fehrmann	2020-07-06 16:43
2958	Atlas	Hardware Repair	Assigned	Normal	List of faulty memory in the Megware 2020 nodes	Henning Fehrmann	Henning Fehrmann	2020-05-20 11:48
2940	Atlas	ToDo	New	Normal	check condor features for the buster cluster 2020	Henning Fehrmann	Henning Fehrmann	2020-01-06 10:57
2923	Atlas	ToDo	Assigned	Urgent	Monitor work/sam servers more closely!	Carsten Aulbert	Henning Fehrmann	2019-09-12 11:01
2665	Atlas	Bug	New	Normal	/etc/network/interfaces.d/interfaces being generated lately in FAI	Henning Fehrmann	Henning Fehrmann	2019-04-09 10:14
2619	Atlas	Bug	Assigned	Normal	node_test.cronjob broken on dev nodes (and possibly others)	Carsten Aulbert	Henning Fehrmann	2019-03-20 15:45
2590	Atlas	Support	Assigned	Normal	Ensure all zpools are generically monitored	Carsten Aulbert	Henning Fehrmann	2019-02-20 21:38
2588	Atlas	Support	Assigned	Urgent	both monitor-server and monitor-nodes are running Jessie and need to be upgraded very soon!	Carsten Aulbert	Henning Fehrmann	2019-04-10 16:38
2582	Atlas	Support	Assigned	Normal	samswitch1/2 documetation	Carsten Aulbert	Henning Fehrmann	2019-02-20 21:27
2576	Atlas	Feature	Assigned	Normal	improve hdd monitoring	Carsten Aulbert	Henning Fehrmann	2019-03-07 14:26
2564	Atlas	ToDo	New	Normal	Shoc test the GPUs	Henning Fehrmann	Henning Fehrmann	2019-02-11 11:51
2527	Atlas	ToDo	Assigned	Normal	Bring data servers under salt control	Carsten Aulbert	Henning Fehrmann	2019-05-22 11:10
2405	Atlas	Support	Assigned	Normal	exchange of door handles or moving of the Rittal door magnet control units	Sven Renas	Henning Fehrmann	2019-02-05 15:42
2326	Atlas	Feature	Assigned	Low	generate dsh lists for atlas	Henning Fehrmann	Henning Fehrmann	2019-02-06 10:38